

Wetland #1 - GPS 21a



Photo 1. View facing north.



Photo 2. View facing east.



Photo 3. View facing south.



Photo 4. View facing west. Lizard's tail is visible in the understory.

Wetland #1 Upland Site - GPS 21b



Photo 5. View from GPS 21 Upland Site. View is facing north.



Photo 6. View facing east.



Photo 7. View facing south.



Photo 8. View facing west. A spoil pile is visible in the background.

Wetland #1 - GPS 22



Photo 9. View of drainage channel near GPS 22. View if facing west.



Photo 10. View of drainage channel facing east.



Photo 11. Wetland area located between GPS 22 and 23. This area was recently disturbed in association with the new house visible in the background. View facing southwest.



Photo 12. Additional view facing southwest at new home construction.

Wetland #1 - GPS 22 and 23



Photo 13. View facing northeast.



Photo 14. View facing east towards GPS 22.



Photo 15. Near GPS 23 facing west.



Photo 16. Near GPS 23 facing west.

Wetland #1 – GPS 23 and 24



Photo 17. View facing southeast near GPS 23.



Photo 18. View facing south from near GPS 24.



Photo 19. View facing north at Wetland 1 near GPS 24.



Photo 20. Small ditch located near GPS 24.

Wetland #1 - GPS 48, 50 and 43



Photo 21. View facing east at GPS50



Photo 22. View of standing water and bulrushes near GPS 48.



Photo 23. Additional view of Wetland 1 near GPS 48.



Photo 24. View facing south at a cleared trail from GPS 43. The centerline of Wetland 1 is located near the end of the cleared trail at the upper edge of the photograph.

Wetland #1 – GPS 43- 45



Photo 25. View from GPS 43 facing south.



Photo 26. View facing east.



Photo 27. View facing northwest.



Photo 28. View at GPS 45.

Wetland #1 - GPS 60,61



Photo 29. View from GPS 60 facing north.



Photo 30. Additional view from GPS 60 facing north.



Photo 31. View facing northeast from near GPS 61.



Photo 32. View facing east from near GPS 61.